





East Branch Delaware River



Stream Corridor Management Plan

Volume 2

December 2007

Prepared by:

**Delaware County Soil and Water Conservation District
Delaware County Planning Department**

In cooperation with:

**The New York City
Department of Environmental Protection**

~ Table of Contents - Volume 2 ~

◆ Table of Contents	i
◆ Figures, Maps, and Tables	iii
◆ 1. Stream Corridor Assessment	1
➤ Dry Brook Sub-basin	5
➤ Tremper Kill Sub-basin	25
➤ Bush Kill Sub-basin	40
➤ Batavia Kill Sub-basin	65
➤ Platte Kill Sub-basin	80
➤ East Branch Delaware River Mainstem	93
➤ East Branch Delaware River Headwaters	103
➤ Terry Clove Sub-basin	106
➤ Fall Clove Sub-basin	108
➤ Mill Brook Sub-basin	110
◆ 2. Geology and Soils	
➤ Geology	
▪ Bedrock Geology	112
▪ Glacial Geology	114
▪ Applied Geology	115
➤ Soils	117
➤ Wetland	118
▪ Wetland Types	121
▪ East Branch Watershed Wetland Inventory	122
▪ Significance of Wetlands	125
▪ Wetland Function in the East Branch Watershed	127
▪ Protecting Wetlands	131
◆ 3. Principles of Stream Science	133
▪ Watershed Characteristics	134
▪ Sediment Balance	136
▪ Stream Feature	138
➤ Stream Morphology and Classification	140
▪ Channel Disturbance and Evolution	144
➤ Human Activities and Impacts on Stream Health	146
▪ Agricultural Influence	146
▪ Highway/Public Utility Infrastructure Influence	147
▪ Residential Development Influence	148
➤ Applying Stream Science to Stream Management	150
▪ A Look to the Future	150
◆ 4. Fisheries and Wildlife	
➤ Fish Species	156
▪ Public Use and Angling	156
▪ Fish Habitat Protection	157
➤ Wildlife	158

◆ 5. Riparian Vegetation	
➤ General Concepts of Riparian Vegetation Ecology	159
▪ Natural Disturbance and its Effects on Riparian Vegetation	160
➤ Forest Land Cover	161
➤ Invasive Plants and Riparian Vegetation	162
▪ Common Reed	163
▪ Purple Loosestrife	163
▪ Garlic Mustard	164
▪ Other Invasive Species	164
▪ Japanese Knotweed	165
◆ 6. Land Use	172
➤ Major Economic Land Uses of the East Branch Delaware River Watershed	173
▪ Forestry	173
▪ Agriculture	174
▪ Bluestone	174
◆ 7. Water Quality	176
◆ 8. Permitting Requirements	
➤ NYSDEC Permit Requirements	193
➤ U.S. Army Corps of Engineers Permit Requirements	194
➤ Erosion and Sediment Control	
▪ Stormwater Pollution Prevention Plan	195
• <i>NYSDEC Requirements</i>	195
• <i>New York City Requirements</i>	195
• <i>Local Requirements</i>	196
◆ 9. Flood Protection and Recovery	
➤ Avoiding Flood Losses	197
➤ Flood Recovery	199
➤ Flood Hazard Mitigation	200
➤ Citizen Flood Response	202
▪ June 2007 Flood Event	203
• <i>Holliday Brook</i>	203
• <i>Beech Hill</i>	205
➤ Delaware County's System for Flood Response	205
◆ 10. Watershed Programs	
▪ Watershed Agricultural Council	208
▪ Watershed Agricultural Program	208
▪ Watershed Forestry Program	208
▪ Delaware County Action Plan	209
▪ Stream Corridor Management	210
▪ Stormwater Management	210
▪ Highway Management Activities	211
▪ Catskill Watershed Corporation	212
▪ Conservation Reserve Enhancement Program	212
◆ Glossary	213
◆ References	222

~ Volume 2 - Section 1 - Sub-basins ~

REACH MAPS

Dry Brook		Bush Kill		Batavia Kill	
DrB 01.....	Page 14	BsK 01.....	48	BatK 01.....	69
DrB 02.....	15	BsK 02.....	49	BatK 02.....	70
DrB 03.....	16	BsK 03.....	50	BatK 03.....	71
DrB 04.....	17	BsK 04.....	51	BatK 04.....	72
DrB 05.....	18	BsK 05.....	52	BatK 05.....	73
DrB 06.....	19	BsK 06.....	53	BatK 06.....	74
DrB 07.....	20			BatK 07.....	75
DrB 08.....	21	East Branch Mainstem		BatK 08.....	76
DrB 09.....	22	EBMS 01.....	99	BatK 09.....	77
DrB 10.....	23	EBMS 02.....	100	BatK 10.....	78
		EBMS 03.....	101		
Tremper Kill		Vly Creek		Platte Kill	
TrK 01.....	29	VIC 01.....	55	PK 01.....	84
TrK 02.....	30	VIC 02.....	56	PK 02.....	85
TrK 03.....	31	VIC 03.....	57	PK 03.....	86
TrK 04.....	32	VIC 04.....	58	PK 04.....	87
TrK 05.....	33	VIC 05.....	59	PK 05.....	88
TrK 06.....	34	VIC 06.....	60	PK 06.....	89
TrK 07.....	35	VIC 07.....	61	PK 07.....	89
TrK 08.....	36	VIC 08.....	62	PK 08.....	89
TrK 09.....	37	VIC 09.....	63	PK 09.....	89
TrK 10.....	38			PK 10.....	89
				PK 11.....	91

TABLES

Table 1.1.....	East Branch Delaware River Sub-basins.....	Page 1
Table 1.2.....	Significant Findings at Reaches DrB 03, 04, and 06.....	9
Table 1.3.....	British Columbia Channel Assessment Findings.....	10
Table 1.4.....	Reaches Containing Narrow Buffers.....	26
Table 1.5.....	Stream Dimensions.....	42

FIGURES

Figure 1.1.....	Bedrock Outcrop on Dry Brook Mainstem.....	Page 5
Figure 1.2.....	Data Collection along Dry Brook.....	6
Figure 1.3.....	Dry Brook Mainstem.....	7
Figure 1.4.....	Stream Alignment at Bush Kill Confluence in 2001.....	8
Figure 1.5.....	Section of Flood Insurance Rate Map for the Arkville Area.....	12
Figure 1.6.....	Rock Revetment Along Ulster County Route 49.....	12
Figure 1.7.....	Vly Creek Step Pool Sequence.....	40
Figure 1.8.....	Failing Revetment Wall.....	43

Figure 1.9	Revetment for Road Protection	44
Figure 1.10	Lake Switzerland Post-Dam Removal	44
Figure 1.11	June 2006 Knotweed Growth	45
Figure 1.12	August 2006 Knotweed Growth	45
Figure 1.13	September 2007 Knotweed Growth	46
Figure 1.14	Village of Margaretville	93
Figure 1.15	Binnekill and Bull Run Tributaries	94
Figure 1.16	Binnekill Headwall	95
Figure 1.17	Golf Course	96

~ Volume 2 - Section 2 - Geology and Soils ~

MAPS

Map 2.1	Surficial Geology	Page 112
---------	-------------------	----------

TABLES

Table 2.1	Bedrock Types in the East Branch Basin	Page 113
Table 2.2	Summary of Wetlands Information for East Branch	124
Table 2.3	Wetlands Density in the East Branch Watershed	125

Figures

Figure 2.1	Wetland Near the Village of Roxbury	Page 120
Figure 2.2	Landscape Position of Palustrine Wetlands	122
Figure 2.3	Small Scale Portion of Wetlands Near Roxbury	128
Figure 2.4	Location of DEC Protected Wetlands Near Roxbury	132

~ Volume 2 - Section 3 - Principles of Stream Science ~

FIGURES

Figure 3.1	Stream Ordering and Dendritic Stream System	Page 133
Figure 3.2	The Hydrologic Cycle	134
Figure 3.3	Daily Mean Discharge Curve	135
Figure 3.4	Sediment Balance	137
Figure 3.5	Entrenchment of Various Stream Types	138
Figure 3.6	Typical Riffle-Pool Sequence	139
Figure 3.7	Stream Type Delineative Criteria	140
Figure 3.8	Flow Responses to Precipitation	141
Figure 3.9	Radius of Curvature	143
Figure 3.10	Profile View of Channel Evolution Sequence	144
Figure 3.11	Stream Evolutionary Sequence	145
Figure 3.12	Streambank Impacted by Cattle	146
Figure 3.13	Dry Brook Road Culvert	147
Figure 3.14	Bridge at Erpf Road	148
Figure 3.15	Regional Hydraulic Relationship Curves	151

Figure 3.16	Stream Types	152
Figure 3.17	Functioning Floodplain Along NYS 30	153
Figure 3.18	Root wad Installation Taken after the 9/18/04 Storm	153
Figure 3.19	Rock Cross-Vane	154
Figure 3.20	Water Flow creating Point Bar	155
Figure 3.21	Looking Upstream at Point Bar in Tremper Kill	155

~ Volume 2 - Section 4 - Fisheries and Wildlife ~

FIGURES

Figure 4.1	Brown Trout	Page 156
------------	-------------	----------

~ Volume 2 - Section 5 - Riparian Vegetation ~

FIGURES

Figure 5.1	A Healthy Riparian Community	Page 159
Figure 5.2	Channel-wide Debris Jam	160
Figure 5.3	Phragmites australis	163
Figure 5.4	Purple Loosestrife	163
Figure 5.5	Garlic Mustard	164
Figure 5.6	Japanese Knotweed in the Town of Halcott	165
Figure 5.7	Knotweed Growing Amongst Corn	166
Figure 5.8	Series of Knotweed Photographs	167

TABLES

Table 5.1	Regional Agencies and Organizations	Page 171
-----------	-------------------------------------	----------

~ Volume 2 - Section 6 - Land Use ~

FIGURES

Figure 6.1	Pepacton Land Use/Land Cover	172
------------	------------------------------	-----

TABLES

Table 6.1	Land Ownership By Category (stream miles)	173
Table 6.2	Dairy Farms of the East Branch Delaware River Watershed	174

~ Volume 2 - Section 7 - Water Quality ~

FIGURES

Figure 7.1	Light Scattering Caused by Suspended Particles in Water	180
Figure 7.2	Annual Median Box Plot for Selected Stream Sites	182
Figure 7.3	NYCDEP Biomonitoring Sites	190
Figure 7.4	Water Quality Scores for Delaware Streams	191

TABLES

Table 7.1..... Stream Classifications..... 177
Table 7.2..... Rationale for Macroinvertebrates Community Analysis..... 189

~ Volume 2 - Section 9 - Flood Protection and Recovery ~

FIGURES

Figure 9.1..... Flood aftermath on Holliday Brook on City Property..... 203
Figure 9.2..... NYS DOT Post Flood Recovery of Holliday Brook..... 203
Figure 9.3..... Holliday Brook After Construction with Cross Vane Structure..... 204
Figure 9.4..... Holliday Brook After Construction..... 204

Maps

Map 9.1..... Location of Holliday Brook and Beech Hill..... 205